



PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

| In re Patent of: |) |
|----------------------------------|-----------------------------|
| | : Examiner: Courtney Thomas |
| TOSHIHIKO OUCHI ET AL. |) |
| A 1 N 00/510 /50 | : Group Art Unit: 2882 |
| Appl. No.: 09/519,672 |) |
| Filed: March 6, 2000 | ; |
| riled. Water 0, 2000 | <i>)</i> · |
| For: SURFACE-TYPE OPTICAL |) |
| APPARATUS | Certificate |
| | MAY 3 1 2005 |
| U.S. Patent No.: US 6,852,968 B1 | of Correction |
| |) or Correction |
| Issued: February 8, 2005 | : |
| |) May 24, 2005 |

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION UNDER RULE 322

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes. A Certificate of Correction form, in duplicate, is enclosed.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Peter Saxon

Attorney for Patentees Registration No. 24,947

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200
NY_Main 497366v1

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,852,968 B1

DATED

February 8, 2005

INVENTOR(S) :

TOSHIHIKO OUCHI ET AL.

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON COVER PAGE (30) FOREIGN APPLICATION PRIORITY DATA:

Foreign Application Priority Data,

"11/059533

11/059535

11/059541" should read

--11-059533 11-059535 11-059541--.

COLUMN 3:

Line 28, the space after "removed." should be deleted. Line 29, "Thus," should read --removed. Thus,--.

COLUMN 5:

Line 3, "<n-side" should read --n-side--. Line 60, "substrate-can" should read -- substrate can--.

COLUMN 6:

Line 49, "supporter-as" should read --supporter as--.

COLUMN 7:

Line 4, "also-directed" should read -- also directed--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

PATENT NO. <u>US 6,852,968 B1</u> No. of add'l. copies

@ 30¢ per page

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,852,968 B1

DATED

February 8, 2005

INVENTOR(S) :

TOSHIHIKO OUCHI ET AL.

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 14:

Line 12, "SiN₁" should read --SiN_x--.

COLUMN 15:

Line 18, "of." should read --of--;

Line 61, the space after "used." should be deleted; and

Line 62, "¶ Further," should read --Further,--.

COLUMN 16:

Line 45, "SiN" should read --SiN_x--.

Line 50, "SiN" should read --SiN_x--.

COLUMN 18:

Line 25, "groove." should read --groove--.

COLUMN 21:

Line 10, "n-diffused" should read --n⁺-diffused--;

Line 22, "200 A" should read --200 Å--; and

Line 63, "p-doped" should read --p⁺-doped--.

COLUMN 22:

Line 58, "SiN," should read --SiN_v--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) NY_Main 497366v1

PATENT NO. <u>US 6,852,968 B1</u>

No. of add'l. copies @ 30¢ per page



JUN 0 1 -2005

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,852,968 B1

DATED

February 8, 2005

INVENTOR(S) :

TOSHIHIKO OUCHI ET AL.

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 24:

Line 19, "Cz 15" should be deleted.

COLUMN 25:

Line 32, "SiN" should read --SiN_x--; and Line 54, "30" should read --30%--.

COLUMN 29:

Line 26electrode As, "" should read --electrode.--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

PATENT NO. <u>US 6,852,968 B1</u>

Form PTO 1050 (Rev. 3-82) NY_Main 497366v1

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,852,968 B1

DATED

February 8, 2005

INVENTOR(S) :

TOSHIHIKO OUCHI ET AL.

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 31:

Line 10, "p-A1 $_{0.3}$ GaO $_{0.7}$ As" should read --p-A1 $_{0.3}$ Ga $_{0.7}$ As--; and Line 33, "SiN" should read --SiN_x--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

PATENT NO. <u>US 6,852,968 B1</u>

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

JUN 0 1 2005

Staple Here Only! WNL SUNJE S

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. :

US 6,852,968 B1

DATED

February 8, 2005

INVENTOR(S) :

TOSHIHIKO OUCHI ET AL.

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON COVER PAGE (30) FOREIGN APPLICATION PRIORITY DATA:

Foreign Application Priority Data,

"11/059533

11/059535

11/059541" should read

--11-059533 11-059535 11-059541--.

COLUMN 3:

Line 28, the space after "removed." should be deleted. Line 29, "¶ Thus," should read --removed. Thus,--.

COLUMN 5:

Line 3, "<n-side" should read --n-side--. Line 60, "substrate-can" should read --substrate can--.

COLUMN 6:

Line 49, "supporter-as" should read --supporter as--.

COLUMN 7:

Line 4, "also-directed" should read -- also directed--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,852,968 B1

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82) NY_Main 497366v1

PRINTER'S TRIM LINE Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,852,968 B1

DATED

February 8, 2005

INVENTOR(S) :

TOSHIHIKO OUCHI ET AL.

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 14:

Line 12, "SiN₁" should read --SiN_x--.

COLUMN 15:

Line 18, "of." should read --of--;

Line 61, the space after "used." should be deleted; and

Line 62, "Further," should read --Further,--.

COLUMN 16:

Line 45, "SiN" should read --SiN,--.

Line 50, "SiN" should read --SiN_x--.

COLUMN 18:

Line 25, "groove." should read --groove--.

COLUMN 21:

Line 10, "n-diffused" should read --n⁺-diffused--;

Line 22, "200 A" should read --200 A--; and

Line 63, "p-doped" should read --p⁺-doped--.

COLUMN 22:

Line 58, "SiN," should read --SiN,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

NY_Main 497366v1

PATENT NO. US 6,852,968 B1

No. of add'l. copies @ 30¢ per page

Stable Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,852,968 B1

DATED

February 8, 2005

INVENTOR(S) :

TOSHIHIKO OUCHI ET AL.

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 24:

Line 19, "Cz 15" should be deleted.

COLUMN 25:

Line 32, "SiN" should read --SiN_x--; and Line 54, "30" should read --30%--.

COLUMN 29:

Line 26electrode As, ** should read --electrode.--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. <u>US 6,852,968 B1</u>

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82) NY_Main 497366v1

JUN 0 1 2005

Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,852,968 B1

DATED

February 8, 2005

INVENTOR(S) :

TOSHIHIKO OUCHI ET AL.

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 31:

Line 10, "p-A1 $_{0.3}$ GaO $_{0.7}$ As" should read --p-A1 $_{0.3}$ Ga $_{0.7}$ As--; and Line 33, "SiN" should read --SiN $_x$ --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. <u>US 6,852,968 B1</u>

No. of add'l. copies @ 30¢ per page



USPTO CHECK REQUEST (MISCELLANEOUS FEES)

(New York Office)

CLIENT NAME:

Canon Inc.

CLIENT/MATTER NO.:

03560.002544.

APPLICATION NO.:

09/519,672

USER ID NO.:

00110

| Code | Item | Amount |
|------|--|----------|
| 1136 | Assign. Recordal Fee | |
| 1137 | Extension | |
| 1138 | Notice of Appeal | |
| 1140 | Cert. of Correction | \$100.00 |
| 1122 | Maintenance Fee | |
| 1143 | Petition | |
| 1200 | Declaration Surcharge | |
| 1201 | Information Disclosure Statement | |
| 1202 | Terminal Disclaimer | |
| 1203 | Request for 3 Month Suspension of Time | |
| 1141 | Trademark Sec. 8; 15 | |
| 1142 | Trademark Renewal | |
| 1144 | Other | |

DATE OF DISBURSEMENT: 05/23/2005

PRINT DATE: 17-May-2005 CHECK REQUEST ID: 39,492